



**HI-LITE MFG.
CO., INC**



13450 Monte Vista Avenue
Chino, California 91710

Telephone: (909) 465-1999
Toll Free: (800) 465-0211

Fax: (909) 465-0907
www.hilitemfg.com

Mounting Instructions for HSC Canopy

1. Disconnect power at main electrical box before installing fixture.
2. Align rotating ball in canopy to accommodate size of connecting stem (1/2" or 3/4").
3. Attach shade to bottom of stem using thread joint compound or thread sealant.
4. Screw top of stem into canopy, thread wires through canopy and use wire nuts to connect black to hot and white to neutral.
5. Ground green wire at grounding screw in junction box.
6. Align canopy mounting holes with junction box and secure with 8-32 screws.



**HI-LITE MFG.
CO., INC**

13450 Monte Vista Avenue
Chino, California 91710

Telephone: (909) 465-1999
Toll Free: (800) 465-0211

Fax: (909) 465-0907
www.hilitemfg.com

Mounting Instructions for HSC Canopy

1. Disconnect power at main electrical box before installing fixture.
2. Align rotating ball in canopy to accommodate size of connecting stem (1/2" or 3/4").
3. Attach shade to bottom of stem using thread joint compound or thread sealant.
4. Screw top of stem into canopy, thread wires through canopy and use wire nuts to connect black to hot and white to neutral.
5. Ground green wire at grounding screw in junction box.
6. Align canopy mounting holes with junction box and secure with 8-32 screws.

